

## **Building Dashboard**

City Hall			14 Court Square				
Building Data							
Structural Details		HVAC		Condition	Appliances	Type/age	
Year Built	1848; occupied as City Hall since 1964	Heating System	VRF heat pumps Gas-fired Steam as backup	EXCELLENT GOOD	Interior Lighting	all upgraded to LEDs 2018	
Square footage	16,430	Heat Distribution	2018 - Heat pump units installed in	EXCELLENT	Exterior Lighting	LEDs in Parking Lot/Building exterior	
Envelope	Brick Envelope, Vinyl covered wood frame roof, Vinyl Replaced 2012	Air Conditioning	offices and hallways	EXCELLENT	Refrigerator	2016 - New Energy Star	
Roof	Both Gable and Flat Roof Replaced in 2018	Ventilation	Passive	N/A	Vending Machine	None	
Windows	Double Pane Installed - 2012	Hot Water Heater	2016 - Heat Pump Water Heater	EXCELLENT	Water Fountains	New in 2017	
Insulation	Walls - None (solid brick) Attic - 12" Loose Fiberglass	Emergency Generator	150 kW Diesel	EXCELLENT			

Building Summary

Electric Service Rate Class


Average Monthly Demand (kW)

Contains offices for the Mayor, Town Clerk, Treasurer, Licensing, Accounting, Energy, Assessors, IT, and Human Resources. 2008 - Boiler replaced. 2012 - Windows and siding replaced. 2013 - Annex Removed. 2014 - Boiler burner changed from oil to gas. 2018 - Heating and cooling systems upgraded to VRF Heat Pumps.

Challenges: Solid masonry construction does not allow for wall insulation

Energy Profile - FY2021				
Energy Usage				
Electric (kWh)	Heat (therms)	EUI (kBTU/sqft)		
182,320	3	38		
EUI ≤ 35 Meets Zero Energy Goal	EUI = 35-50 Efficient	EUI >50 Priority to Improve		
Annual Energy Cost				
Electric	Gas/Oil	Total		
\$31,272	\$153	\$31,425		
Berkshire Gas Rate C	<u>G41</u>			

34.5



Completed Work						
Fiscal Year	Project	Project Cost	Grants/Rebates	Life Expectancy	Warranty	
2012	Window Replacement (ARRA Funding)	N/A	N/A	10-20 years	expired	
2017	Heat Pump Hot Water Heater	\$1,037	\$173	10-12 years	10 year	
2017	Diesel Emergency Generator Installation (replacing smaller generator installed in 2016)	\$60,000	none	10,000 to 30,000 hours	TBD	
2018	Roof replacement - shingles and membrane	\$85,000	none	30-40 years	30 yrs - membrane 40 yrs - architectural shingles	
2019	Air-Source Heat Pumps Installation (Green Communities Grant)	\$138,525	\$96,845	20+ years	10 years - compressor & parts	
2019	LED lighting upgrade	\$11,479	\$5,222	20+ years	5 years	

Audits/Assessments			
Fiscal Year	Туре	Findings	
2009	Siemens Whole building assessment	Report available upon request	
2014	Clearesult	Suggestions for improving insulation, ventilation, and steam traps	
2016	CET Insulation Audit	Additional attic insulation unnecessary - would not be eligible for incentives	